

**R66 SERVICE BULLETIN SB-35**

**DATE:** 02 December 2019

**TO:** R66 Owners, Operators, and Maintenance Personnel

**SUBJECT:** Chin Inspection Hole and Access Cover

**ROTORCRAFT AFFECTED:** R66 Helicopters S/N 0003 thru 0027.

**TIME OF COMPLIANCE:** Within next 500 flight hours or by 30 November 2020, whichever occurs first.

**BACKGROUND:** This bulletin requires cutting a hole and installing an access cover in the chin to facilitate inspection of tail rotor flight controls.

---

**COMPLIANCE PROCEDURE:**

1. For each affected helicopter, order one KI-233-2 Chin Access Cover Installation Kit.
2. Install KI-233-2 kit per kit instructions.
3. Make appropriate maintenance record entries.

**APPROXIMATE COST:**

Parts: \$37 for KI-233-2 Kit if ordered by 30 November 2020.

Labor: Approximately 2.5 man-hours.